Hyundai HQP 421 SR 42” Plasma TV
Power supply is labelled LJ44-00068A v3.0 PS-423-SR and is common in early 42” plasma TV’s

Fault Symptoms:

- Turns on then off after about 10 seconds.
- Red “Protection” LED comes on.

Check / replace components in VE power supply area as shown below
Adjust VE for +165V or as shown on PDP label



Info sourced from www.JTelectronics.co.nz